

Fig. 1A




Fig. 1B




Fig. 2




Fig. 3




Fig. 3A





Fig. 4



55.5




Fig. 7




Fig. 3





Fig. 9

FIG. 9A










FIG. 10








File 12





६७.१५




FIG. 15




Fig. 16




Fig. 16A




Fig. 17

Fig. 18A

302




Fig. 18

U.S. Pat. No. 4,800,000




Fig. 19




Fig. 20




Fig. 21




FIG. 22

602
↙




Fig. 23

FIG. 24




Fig. 24

702




FIG. 25




FIG. 26

FIG. 27




Fig. 27




Fig. 28